

# Release Notes



April 2022

# Updated Network Discovery Tool IP-Finder for V1008-WIR-180-1, V1020-WIR-180-1, V1020-WIR-360, V2020-WIR-360 and V2032-WIR-360 Multi-Sensor Cameras

## General Description

Vicon has released an updated network discovery tool, IP-Finder, for the cameras listed below.

This replaces the IP-Finder 1.0.9 utility that was already in place for existing multi-sensor cameras. The new IP-Finder utility adds support for the new V20xx-WIR-360x camera and is backwards compatible with the earlier multi-sensor cameras.

| For cameras   | Product Code   | Older software  | Newest software  |
|---|--|-----------------|------------------|
| V1008-WIR-180-1<br>V1020-WIR-180-1<br>V1020-WIR-360<br>V2020-WIR-360<br>V2032-WIR-360 | 10486-05<br>10487-05<br>10517-10<br>10517-20<br>10517-25 | IP-Finder 1.0.9 | IP-Finder 1.0.13 |

#### Vicon Production

The latest firmware and discovery tool are available on Vicon's website. A link is provided in the installation section of this document. Manufacturing will use the new software for new camera production.

#### **Software Installation**

- Unpack the contents of the ZIP file called VICON-IP-FINDER\_v1.0.13.zip onto a PC.
- Run the software installer VICON IP-FINDER Ver.1.0.13-Setup.msi
- The ZIP file also contains an IP-Finder user guide IP-FINDER\_User\_Manual.pdf

The software can be downloaded from Vicon's website:

https://www.vicon-security.com/software-downloads-library/vicon-camera-software/



# Release Notes



#### **Fixed issues**

## **Default Browser**

An issue was fixed where the IP-Finder tool would always open Internet Explorer when a camera is clicked, regardless of the PC's configured default browser. It now opens the browser that is configured as the default browser program on the PC.

# Crash during FW upgrade

It was possible that the IP-Finder tool would crash when a firmware update was performed. This has been corrected.

# Firmware update failed.

It was possible that a camera firmware update would fail due to some specific timing issues. The process has been made more robust.

## Support for new camera models

Improved support for the new V2020 and V2032 cameras.