# Release Notes

May 2017

## HDExpress Firmware Release

## General Description

Vicon has released updated firmware for the HDExpress line of NVRs.

This release includes firmware updates to the latest models of the HDExpress NVRs (ending with L3 and P3). **Older** hardware models do not get updated anymore.

| Model (all drive options) | Latest Firmware Version | New Firmware Version |
|---|---|---|
| **HDXPRES-4L3** | 39110.1.108120.96 | 39110.1.108605.96 |
| **HDXPRES-8L3** | 39210.1.108120.96 | 39210.1.108605.96 |
| **HDXPRES-16L3 (1U)** | 39310.1.108120.96 | 39310.1.108605.96 |
| **HDXPRES-16P3 (2U)** | 43310.1.108120.96 | 43310.1.108605.96 |

## New Features and Operational Changes

➢ This updated firmware contains general fixes improving the overall stability and ONVIF support
➢ Corrected a system limitation prevent from rebooting the unit via web interface
➢ PTZ speed control improvements

## Who Should Install the New Package?

This is not a mandatory update. Vicon recommends updating to the latest firmware in order to ensure all known issues are fixed.

## Obtaining Firmware

These firmware versions are now available on Vicon's website

http://www.vicon-security.com/software-downloads-library/express-hdexpress-software/

## Licensing

This firmware update does not require any licensing

Written by Guy Arazi