



Release Notes

March 2021

Updated Network Discovery Tool IP-Finder for V1020-WIR-360, V1008-WIR-180-1, V1020-WIR-180-1 Multi-Sensor Cameras

General Description

Vicon has released an updated network discovery tool, IP-Finder, for the cameras listed below.

This replaces the IP-Finder 1.0.6 utility that was already in place for the V1008-WIR-180-1 and V1020-WIR-180-1 cameras. The new IP-Finder utility adds support for the new V1020-WIR-360 camera and is backwards compatible with the older V1008-WIR-180-1 and V1020-WIR-180-1 cameras.

For cameras	Older software	Newest software
V1008-WIR-180-1 V1020-WIR-180-1 V1020-WIR-360	IP-Finder 1.0.6	IP-Finder 1.0.9

Vicon Production

The latest firmware and discovery tool are available on Vicon's website. A link is provided in the installation section of this document. Manufacturing will use the new software for new camera production.

Software Installation

- Unpack the contents of the ZIP file called VICON-IP-FINDER_v1.0.9.zip onto a PC.
- Run the software installer VICON_IP-FINDER_Ver.1.0.9-Setup.msi
- The ZIP file also contains an IP-Finder user guide IP-FINDER_User_Manual.pdf

The software can be downloaded from Vicon's website:

<https://www.vicon-security.com/software-downloads-library/vicon-camera-software/>