

February 2016

Updated Firmware for HDExpress

General Description

Vicon has released updated firmware for certain HDExpress models to allow using them with ViconNet 8.1 in the same way the newer (L3 and P3) models are being used. The firmware also contains the latest bug fixes.

Covered by this version are the HDExpress 4 and 8 channel units with VGA ports as well as the older 16 channel unit. Prior versions of the unit (HDXPRES-4 / 8 without a VGA port) are not expected to be supported in ViconNet.

The updated firmware is as follows:

HD Express model	Firmware	New Firmware	
4 channel (HDXPRES-4V)	36110.1.104701.96	36110.1.106402.96	
8 channel (HDXPRES-8V)	36210.1.104701.96	36210.1.106402.96	
16 channel (HDXPRES-16)	22310.1.104701.96	22310.1.106402.96	

Important note!

These models of the HDExpress do not support the IQeye line of cameras. All newer models (model number ending with L3 and P3) support the IQeye cameras.

See the Vicon website for further details.

Performing Firmware Update

The latest firmware is available on Vicon's website from the Learn and Support menu – Software Downloads – HDExpress software; a link is provided below.

http://www.vicon-security.com/learn-and-support/software-downloads#hdexpress-software-and-firmware

The correct firmware (by model) needs to be placed on a USB thumb drive and plugged into the HDExpress.

- Access the setup menu System System Management.
- Click the button for FW update.
- Select the firmware version from the list and click UPGRADE.

Vicon Release Notes

SYSTEM MANAGEMENT FW UPDATE FACTORY DEFAULT SYSTEM DATA		USB LOAD SAVE	LOAD		
SYSTEM ID			UPGRADE		
	EVICE	NONE			-
EXPIRED TERM OF PASS	/W LIST				
AUTO LOGOUT					
WAITTIME					
POE POWER LIMIT					
AC POWER FREQUENCY					
SWITCH OPERATION MO					
			CLOSE	-	